

SAFE PANEL SYSTEM

SAFE™ 2

A VARIABLE DUROMETER
FLOATING SYSTEM

SAFE PANEL SYSTEM
VARIABLE DUROMETER
FLOATING SYSTEM

Most Popular Floating DIN System.

- ❑ Custom tailored resilience
- ❑ Meets or exceeds all DIN/EN standards
- ❑ Dimensional stability
- ❑ Versatile multi-sport applications



Horner MFMA Maple
2 layers 15/32" rated subfloor
7/16" or 3/4" SAFE™ pad with
variable durometer options



LEED
Options Available

Field houses, competition and multipurpose gymnasiums, collegiate, secondary schools and dance areas.

PERFORMANCE

Meets or exceeds DIN18032-Part II / EN 1490-2006

PERFORMANCE CHARACTERISTICS

- Shock Absorption ✓
- Vertical Deflection ✓
- Area of Deflection ✓
- Ball Bounce ✓
- Surface Friction (Coefficient of Friction/Sliding Coefficient) ✓
- Rolling Load ✓


SPECIFICATIONS

System Thickness*/Pad Options

- 25/32" MFMA Horner Maple:
 - 2 1/2" Floor using 3/4" SAFE pad
 - 2 1/8" Floor using 7/16" SAFE pad
- 33/32 MFMA Horner Maple: Add 1/4"

*System thickness is equivalent to slab depression for new facilities.

MATERIALS

- Option: Specify Horner LongLife™ Maple 
- Subfloor: 2 layers 15/32" rated sheathing or optional 7/16" OSB subfloor
- Vapor retarder

GREEN/LEED OPTIONS

- FSC Maple Flooring MRC 7
- FSC Subfloor Components MRC 7 Exemplary Performance

INSTALLATION REFERENCES

- Seatac YMCA, Seatac, WA
- Maude Clifford Sec., Grand Prairie, Alberta
- Prairie Hill Middle School, Racine, WI
- B. Michael Caudill School, Richmond, KY
- Lake Andres School, Lake Andres, SD



SPECIFY

For extended wear life, choose **Long Life™**. Horner's **Long Life™** flooring is 25/32" northern hard maple with the same wear depth as 33/32" flooring. **Long Life™** provides the ecological, cost savings and availability benefits of a 25/32" floor, with extended wear life. More re-sands, stronger system and economical. Why not value engineer?

HORNER FLOORING is the leading manufacturer of athletic flooring systems used in high-school gyms, college and professional arenas, and public and private training facilities.



HORNER FLOORING COMPANY, INC.
800.380.0119 / www.hornerflooring.com

P.O. Box 380, 23400 Hellman Avenue, Dollar Bay, MI 49922
P: 906.482.1180 / F: 906.482.6115 / info@hornerflooring.com

Please contact us regarding our extended maintenance warranty options.